



ARRIS Lander X3 release 1



OR



Improvements

Some improvements could be made concerning the tube fixation. Indeed the tube clamping system in the servo unit is not very effective. Here they could mill a slot in the metal portion and drill holes through the tube, which would greatly increase the stiffness of the binding.

ARRIS Lander X3 release 2 (Tube fixation modification)

